

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2024

Submitted Date:

01/04/2024

Document Number:

714200517

FIELD INSPECTION FORM

Loc ID 429708 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429709	WELL	PR	01/28/2013	OW	123-35872	COOK 37C-3HZ	PR
429710	WELL	PR	06/01/2020	OW	123-35873	COOK 36N-3HZ	PR
429712	WELL	PR	01/28/2013	GW	123-35874	COOK 37N-E3HZ	PR
429713	WELL	PR	01/28/2013	GW	123-35875	COOK 37N-W3HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at one pumpjack. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.	Date:	11/27/2023

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)	210 BBLS		
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with other tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLS	STEEL AST		

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	429709	Type:	WELL	API Number:	123-35872	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; valves appear to be in an open position.								
Corrective Action:						Date:			
Facility ID:	429710	Type:	WELL	API Number:	123-35873	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; valves appear to be in an open position.								
Corrective Action:						Date:			
Facility ID:	429712	Type:	WELL	API Number:	123-35874	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; valves appear to be in an open position.								
Corrective Action:						Date:			
Facility ID:	429713	Type:	WELL	API Number:	123-35875	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; valves appear to be in an open position.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200302. It appears one out of two previous corrective actions assigned to this location have been completed. The incomplete corrective action is still valid with its original corrective action date. No new corrective actions were observed at the time of re-inspection. Please review narrative below for additional information and details.</p> <p>WEATHER CONDITIONS: sunny, dry ground. On Wednesday, January 3, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at COOK 37C-3HZ (Kerr McGee Oil & Gas Onshore), at location ID: 429708 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be stained soil at one pumpjack. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: November 27, 2023) See attached photos #2. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	01/04/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714200518	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6381229