

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2024

Submitted Date:

01/04/2024

Document Number:

714300014

**FIELD INSPECTION FORM**

Loc ID 324591 Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Peterson, John		jpeter@kpk.com	<a href="#">KPK environmental</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
Kelly Elliot		kaelliott@blm.gov	<a href="#">BLM</a>
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465486	TANK BATTERY	AC	11/19/2020		-	Dwinell Tank Battery	EI

**General Comment:**

NOTE: Physical inspection was conducted by Alex Fischer, due to technical issues inspection manually entered by Kari Brown.

On January 3, 2024, at approximately 12:45 ECMC Environmental Supervisor Alex Fischer conducted an inspection of the KPK Dwinell Tank Battery and Location. Weather was sunny, 7 degrees Fahrenheit, and there was approximately 4 to 6 inches of snow on the ground.

ECMC Staff observed an on-going release at the approximate 4" manifold going from tank to tank on the two (2) westerly 500 bbl, fiberglass produced water tanks. The release was a steady drip. An attempt to stop the leak was apparently made by the operator, as there was some type of tape placed on one of the tanks and manifold where it was leaking.

At approximately 12:59 ECMC Staff called the emergency contact number (303-825-4822) posted on Location. A Lilly (she said she was on payroll for KPK) answered the call. ECMC Staff explained who he was, the Location, and the situation.

At approximately 13:02, Lilly transferred the call to Laura. ECMC Staff explained who he was, the Location, and the situation. Laura stated that she would contact the KPK field office. ECMC Staff stated that he would stop by the field office to see if Jeff Boxley was there.

At approximately 13:20, ECMC Staff stopped in at the KPK field office. Juan with KPK was present and stated that Jeff had just left. ECMC Staff explained the situation and that the release needs to be addressed ASAP. Additionally, ECMC Staff explained to Juan to let KPK Denver know that a spill/release report will need to be filled. Juan stated that he would call Jeff.

At approximately 13:55 ECMC Staff was contacted by Jeff B. Jeff stated that he was in Laramie, Wyoming and he would return yet today (1/3/2024) to address the release and would also get a spill/release report submitted.

NOTE: Physical inspection was conducted by Alex Fischer, due to technical issues inspection manually entered by Kari Brown.

**Inspected Facilities**

Facility ID: 465486 Type: TANK API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: ECMC Staff observed an on-going release at the approximate 4" manifold going from tank to tank on the two (2) westerly 500 bbl, fiberglass produced water tanks. The release was a steady drip.

Corrective Action: Per correspondance on 1/3/2024 Operator shall submit an Initial Form 19 Spill/Release Report for the Spill and immediately initiate spill clean-up activities.

Date: 01/06/2024

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300015	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6381710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6381710</a>