

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2024

Submitted Date:

01/04/2024

Document Number:

693806571**FIELD INSPECTION FORM**Loc ID 322429 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS ST STE 6161City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
Arnim, Rees	713-469-0275	rarnim@locin.energy	Director of Engineering
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119495	PIT	AC	03/27/2017		-	Federal #3-11-8-104 119495	AC
210481	WELL	SI	06/01/2020	GW	045-06237	FEDERAL 3-11-8-104	TA

General Comment:

ECMC staff performed a routine field inspection on 1/3/2024.
Issues were found requiring corrective action. See inspection text and photos for details.
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location**Lease Road:**

Type	Access		
comment:			
Corrective ActionL		Date:	
Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not updated to reflect current operator and emergency contact information.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/11/2024

Emergency Contact Number:

Comment:	see above		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Pump jack in shed with hogwire & T-post		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Separator removed since last inspection		
Corrective Action:		Date:	
Type: Flow Line	# 9		
Comment:	Various size risers left in place from production equipment removal		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	1 gas meter shed removed since previous inspection.		
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		39.381611,-108.963760
Comment:	Disconnected				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Fence and berms removed.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	119495	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	210481	Type:	WELL	API Number:	045-06237	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED									
Comment: Form 6 Doc#403334306 approved 5/9/2023. Expired 11/8/2023.									
Corrective Action: Contact NW area engineer aaron.katz@state.co.us Date: 01/11/2024									
BradenHead									
Date of Last Brhd Test: 05/24/2022 Annual Brhd Completed? No									
Last Brhd Test Results Initial Surf Csg Pressure: 260 Fluid Type: NONE									
End Surf Csg Pressure: 1									
Comment:									
Corrective Action: Date:									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 119495Lat: 39.381543Long: -108.964161Reference Point: SE

Other: _____

Length: 16Width: 16**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:Netting Type: MeshNetting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	115193	400988057	
	115193	400988057	
	119495	400987624	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693806578	Inspection photos 1/3/2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6381939