

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2024

Submitted Date:

01/05/2024

Document Number:

702402798**FIELD INSPECTION FORM**Loc ID 319194 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423907	WELL	SI	03/01/2022	OW	123-33782	STREAR 29-10	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	ag panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	exposed at surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	423907	Type:	WELL	API Number:	123-33782	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: SI, Form 06A Doc # 403108165									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 09/05/2023									
Annual Brhd Completed? Yes									
Last Brhd Test Results									
Initial Surf Csg Pressure: 0									
Fluid Type: None									
End Surf Csg Pressure: --									
Comment:									
Corrective Action:									
Date:									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On Friday 1-5-2024 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location name: Strear 22-10 Location ID # 319194 Well Name: Strear 29-19 API # 05-123-33782 County: Weld Weather: Cloudy, clear and cold. Location: Dry While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed no compliance issues: See attached photos. /No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.	revasr	01/05/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402799	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383490