

Interim and Stormwater Inspection

December 8, 2023

Operator: Verdad Oil & Gas Co- #10651

Location ID: 451659

Inspection Document #: 709400717

Weld County, CO

SESW Section 17 T1N R64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Warner 1N-64W-17
Facility ID: 451659



Photo 1. Photo taken of location permits.



Photo 2. Photo taken of topsoil stockpile. Photo taken facing north.

Inspection Photos
Location Name: Warner 1N-64W-17
Facility ID: 451659

Dec 8, 2023 at 10:51:32 AM
Keenesburg CO 80643
United States



Photo 3. Photo taken of straw crimped soil on south side of pad. Photo taken facing west.

Dec 8, 2023 at 10:51:43 AM
Keenesburg CO 80643
United States



Photo 4. Photo taken of straw crimped topsoil stockpile. Photo taken facing North.

Inspection Photos
Location Name: Warner 1N-64W-17
Facility ID: 451659



Photo 5. Photo taken on top of topsoil stockpile, lacking proper soil protection. Photo taken facing north



Photo 6. Photo of undisturbed vegetated area for reference next to pad. Photo tank facing east.

Inspection Photos

Location Name: Warner 1N-64W-17

Facility ID: 451659



Photo 7. Photo of north side of location. Photo tank facing west.



Photo 8. Photo of bare soil on west side of pad. Photo taken facing south.



Inspection Photos

Location Name: Warner 1N-64W-17

Facility ID: 451659

Dec 8, 2023 at 10:57:02 AM
Keenesburg CO 80643
United States



Photo 9. Photo of outlet of culvert in access road, no soil protection observed or outlet protection. Photo tank facing east.

Dec 8, 2023 at 10:57:08 AM
Keenesburg CO 80643
United States



Photo 10. Photo of trash at entrance of on west side of pad. Photo tank facing northwest.

Inspection Photos
Location Name: Warner 1N-64W-17
Facility ID: 451659

Dec 8, 2023 at 10:57:33 AM
 Keenesburg CO 80643
 United States



Photo 11. Photo taken of inlet of culver on access road, no ditch flows to culvert, no soil protection observed or inlet protection. Photo taken facing west.

FORM 2A
 Rev. 08/13

State of Colorado
Oil and Gas Conservation Commission
 120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 694-2100 Fax: (303) 694-2109

DNR
CO

Document Number:
401273477

Date Received:
05/26/2017

Location ID:
451659

Expiration Date:
08/08/2020

New Location Refile Amend Existing Location Location#:

This Oil and Gas Location Assessment is to be submitted to the COGCC for approval prior to any ground disturbance activity associated with oil and gas operations. Approval of this Oil and Gas Location Assessment will allow for the construction of the below specified Location; however, it does not supersede any land use rules applied by the local land use authority. Please see the COGCC website at <http://cogcc.state.co.us/> for all accompanying information pertinent to this Oil and Gas Location Assessment.

This location assessment is included as part of a permit application.

CONSULTATION

This location is included in a Comprehensive Drilling Plan, CDP # _____

This location is in a sensitive wildlife habitat area.

This location is in a wildlife restricted surface occupancy area.

This location includes a Rule 306.d.(1)(A).i. variance request.

Operator

Operator Number: 10651

Name: VERDAD RESOURCES LLC

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

Contact Information

Name: Kenny Truesax

Phone: (720) 651-8409

Fax: ()

email: Regulatory@verdadoll.com

RECLAMATION FINANCIAL ASSURANCE

Plugging and Abandonment Bond Surety ID: 20170009 Gas Facility Surety ID: _____

Waste Management Surety ID: _____

LOCATION IDENTIFICATION

Name: WARNER

County: WELD Number: 01N-64W-17

Quarter/Quarter: SESW Section: 17 Township: 1N Range: 64W Meridian: 6 Ground Elevation: 5663

Define a single point as a location reference for the facility location. When the location is to be used as a well site then the location must be a well location.

Footage at surface: 210 feet FSL from North or South section line

2401 feet FWL from East or West section line

Latitude: 40.044704 Longitude: -104.575548

PDOP Reading: 1.4 Date of Measurement: 03/16/2017

Instrument Operator's Name: ROSS TODD

Photo 12. Photo taken of copy of 2A on site. No weld county stormwater plan observed.