

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2024

Submitted Date:

01/05/2024

Document Number:

701007901

**FIELD INSPECTION FORM**

Loc ID 321622 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

21 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Rogers, Bob	719-767-8851	brogers@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207545	WELL	PR	11/12/1984	OW	017-06480	MPU 44-26	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Stickers on chemical drum		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Pipe fence around transformer		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and compressor shed		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 2		
Comment:	Meter run on east side of water tank Meter run on south side of vertical treaters		
Corrective Action:		Date:	

Type: Pig Station	# 1		
Comment:	Pig station on south side of oil tanks operated by Plains		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Electric booster compressor in wooden shed		
Corrective Action:			Date:
Type: LACT	# 1		
Comment:	Telemetry equipment, LACT unit in fiberglass shed and transfer pump on east side of oil tanks operated by Plains		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:	Horizontal treater on north side of vertical treater		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	American 640		
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	Electric panel, transformer, cathodic rectifier, chemical drum w/containment, electric panel and elec circ pump at tank battery		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed next to vertical treater		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:	Treater with metal shed		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST		38.885910,-102.740810
Comment:	Black tank on south end of location				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	

Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLs	STEEL AST		38.886420,-102.740720	
Comment:	Blue tanks on the north side of location					
Corrective Action:					Date:	
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No						
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**

Facility ID: 207545 Type: WELL API Number: 017-06480 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for \(Section 25\) 1500' NNE, Central tank battery for \(MPU 22D-25, 22-25 #3, 44-25, 13-25, 44-26\) @ 38.886420/-102.740720](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007925	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383666">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383666</a>