



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good, all five wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	safety fencing around excavation		
Corrective Action:		Date:	

**Equipment:**

Type: Pig Station	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	LOTO and plugged		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 415210 Type: WELL API Number: 123-31010 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment: Form 6A 7-22-2022 well head disconnected with fittings plugged

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/01/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 27 Fluid Type: GAS

End Surf Csg Pressure: 1

Comment: Form 42 Bradenhead abatement 1-5-2023, Messoc unit in place

Corrective Action:  Date:

Facility ID: 415232 Type: WELL API Number: 123-31018 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment: Form 6A 7-22-2022 well head disconnected with fittings plugged

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 07/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

Facility ID: 415233 Type: WELL API Number: 123-31019 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment: Form 6A 7-22-2022 well head disconnected with fittings plugged

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 07/07/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 33 Fluid Type: Water

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

Facility ID: 415246 Type: WELL API Number: 123-31022 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment:

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 07/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

Facility ID: 415247 Type: WELL API Number: 123-31023 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: SITE CONDITION

Comment:

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 07/28/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection at site with 5 TA wells, and meter run. Flow lines and all production equipment removed</a>	kesterm	01/05/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300505	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384146">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384146</a>