

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2024

Submitted Date:

01/08/2024

Document Number:

695109006

FIELD INSPECTION FORMLoc ID 307892 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
WARD, GIENA		gward@ogrisop.com	All Inspections
,		dnr_cogccengineering@state.co.us	
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259210	WELL	SI	02/01/2021	CBM	071-07204	APACHE CANYON 14-16V	TA

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

1

Comment: Corrective Action: Date:

Type: Vertical Separator

1

Comment: Corrective Action: Date:

Type: Other

1

Comment: 25 BBL STEEL ABOVE GROUND PRODUCED WATER TANK WILL HAVE TO BE REMOVED DUE TO WELL BEING TA (UNUSED EQUIPMENT)

Corrective Action: Date:

Type: Pump Jack

1

Comment: WELL IS NOW TA DUE BRIDGE PLUG SET ABOVE PERFS, PUMPJACK ALONG WITH THE CONCRETE PAD WILL NEED TO BE REMOVED FROM LOCATION (UNUSED EQUIPMENT).

Corrective Action: Date:

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action: Date:

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action: Date:

Type: Deadman # & Marked

4

Comment: Corrective Action: Date: **Venting:**

Yes/No NO

Comment: Corrective Action: Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 259210

Type: WELL

API Number: 071-07204

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment:

OPERATOR PERFORMED MIT. OPERATOR HAD TO CHANGE FORM 42 TWICE DUE TO RIG REPAIRS. OPERATOR ATTEMPTED TO MIT WELL ON JAN.3, 2024 WITH AREA COMPLIANCE SPECIALIST ON SITE AND COULD NOT GET A TEST DUE TO FORMATION HEATING WATER IN CSG. OPERATOR CAME BACK THE NEXT DAY JAN. 4, 2024 AND PERFORMED THE MIT (AREA COMPLIANCE SPECIALIST WITNESSED).

CIBP SET 67' ABOVE TOP OF PERFS @1587' W/ TOPP @ 1654'

PHOTO 4: INITIAL MIT PSI 344.8

PHOTO 5: 5 MIN. MIT PSI 344.2

PHOTO 6: 10 MIN. MIT PSI 344.0

PHOTO 7: 15 MIN. FINAL MIT PSI 343.9, TOTAL -.9 LOSS DURING 15 MIN. MIT, -.1 LOSS IN LAST 5 MIN. OF MIT.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/29/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Workover

Comment:

OPERATOR PERFORMED MIT.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 268870Lat: 37.078350Long: -104.957210Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: NOOil Accumulation: YES2+ feet Freeboard: YESComment: Corrective Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109009	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6385225