

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2024

Submitted Date:

01/09/2024

Document Number:

708902744

**FIELD INSPECTION FORM**

Loc ID 335134 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

23 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210974	WELL	PR	12/28/1990	CBM	045-06732	DOE FED 9-17 MV	PR
210982	WELL	PR	09/03/1991	GW	045-06740	DOE FED 19-17 W	PR
278405	WELL	PR	06/21/2005	GW	045-10877	FEDERAL RWF 543-17	PR
278406	WELL	PR	04/10/2006	GW	045-10876	FEDERAL RWF 443-17	PR
278407	WELL	PR	06/21/2005	GW	045-10875	FEDERAL RWF 343-17	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 01/08/2024 at approximately 10:30 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC DOE FED 9-17 MV Pad. Location # 335134 in Garfield County Colorado.  
Please refer to inspection 708901113 conducted on 07/21/2023, previous corrective actions have been completed.  
Location is within High Priority/Density Habitat areas.  
Drainage contributes to the Colorado River.  
While there, I observed normal production operations.  
  
This is a summary of inspection report.  
  
Shared facilities with the RMV 59-17 pad, location # 323926. Location is inside the Garfiled County landfill.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	RWF 543-17 & DOE 9-17 MV wellhead signs weathered & cracking but still legible		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign weathered & cracking but still legible		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Plunger Lift	# 4	
Comment:	DOE 9-17W well is not on plunger lift. Remaining 4 wells are on plunger lift.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 6	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:	Marked	
Corrective Action:		Date:
Type: Bradenhead	# 5	
Comment:	RWF 543-17 well has a Taylor plug located on bradenhead, bradenhead valve is accessible. Remaining 4 wells have no form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Telemetry	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:		Centralized containment			
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity) 80 bbl					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:					Date:
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					Date:
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					Date:
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	<u>210974</u>	Type:	<u>WELL</u>	API Number:	<u>045-06732</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>210982</u>	Type:	<u>WELL</u>	API Number:	<u>045-06740</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well is not on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>278405</u>	Type:	<u>WELL</u>	API Number:	<u>045-10877</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>278406</u>	Type:	<u>WELL</u>	API Number:	<u>045-10876</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>278407</u>	Type:	<u>WELL</u>	API Number:	<u>045-10875</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Other						Hay bales
		Gravel				Sparse
Berms						
		Culverts				
		Ditches				
Ditches						
Waddles						
		Compaction				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Shared facilities with the RMV 59-17 pad, location # 323926. Location is inside the Garfield County landfill.	smelserw	01/09/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902745	Inspection 708902744 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387168</a>
708902746	Inspection 708902744 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387169">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387169</a>