

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2024

Submitted Date:

01/08/2024

Document Number:

701007895

FIELD INSPECTION FORM

Loc ID 321831 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10634
Name of Operator: P O & G OPERATING LLC
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Nash, Charlotte	(713) 589-8186	charlotte_nash@pogresource.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208145	WELL	SI	10/01/2023	OW	017-07080	HARKER RANCH MORROW UNIT (HRMU 7	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground and pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign by tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks. Install capacity labeling		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Rods, tubing and misc stored on location. Used as storage yard for nearby locations		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	American 228		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	150bbl FWKO on east side of metal shed		
Corrective Action:		Date:	

Type: Ancillary equipment	# 6		
Comment:	Electric panel, cathodic rectifier, propane tank for ECD, chemical tank w/containment, triplex and electric panel in metal shed		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 2		
Comment:	Treaters are disconnected and not in use		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	ECD on west side of tank battery		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		38.935370,-102.177930
Comment:	Green tank next to metal building for injection pump				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.935370,-102.177930
Comment:	Tan overflow tank for 200bbl tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: Shared berms			
Corrective Action:		Date:	
Contents	#	Capacity	Type
CRUDE OIL	5	400 BBLs	STEEL AST
Tank ID		SE GPS	
		38.935370,-102.177930	
Comment: 3-Tan tanks have false bottoms. SE tan tank has hatch removed and not in use 2-Silver tanks			
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 208145 Type: WELL API Number: 017-07080 Status: SI Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(HRMU 3, 5, 6, 7, 9-12\) @ 38.935370/-102.177930](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007931	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6387600