

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2024

Submitted Date:

01/04/2024

Document Number:

699805722**FIELD INSPECTION FORM**Loc ID 385333 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaulo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214054	WELL	SI	12/01/2014	OW	067-05346	DUDLEY 2 (OWP)	PA

General Comment:**ECMC Inspection Report Summary**

On 10/12/2023 I, OWP Specialist Corey DePaolo,

Witnessed the plugging and abandonment of the RED MESA HOLDINGS/O&G LLC DUDLEY-N33N12W /23SWNW (OWP)

Location #385333 in La Plata County Colorado.

-OWP Plugging operations consisted of setting two plugs over the course of 2 days. One cement plug at PBTD and surface. The well was cut and capped on 10/12/2023.

This is a summary of the inspection report

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	All signs have been removed from location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Other	#			corrective date
Comment:	All equipment has been removed from location			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	214054	Type:	WELL	API Number:	067-05346	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name:					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 913' to 0'					Cement Volume (sx): 135				
Good Return During Job: YES					Cement Type: Prem G				
Comment:					OWP Plugging operations consisted of setting two plugs over the course of 2 days. One cement plug at PBTD and surface. The well was cut and capped on 10/12/2023.				
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						

Comment:

Corrective Action:

Date:

Pits:

☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Related Facility for comments	depaoloc	01/04/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805723	Photo log Insp. #699805722	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6388204