

# Final Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313647

Inspection Document #: 708200844

Morgan County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Sand River Unit 13  
Location ID: 313647



**Photo 1.** Facing west along the eastern part of the access road. The access road has not been reclaimed per Rule 1004; additional reclamation activities are required.

Inspection Photos  
Location Name: Sand River Unit 13  
Location ID: 313647



**Photo 2.** Facing east near the former well location; see comments in Photo 1.

Inspection Photos  
Location Name: Sand River Unit 13  
Location ID: 313647



**Photo 3.** Google Earth aerial imagery taken circa 09/2023. Photo illustrates that the access road has not been reclaimed. Portions of the access road associated with Well API #087-05078, highlighted in red, will need to be reclaimed (e.g. contoured, regraded, reseeded, etc).

Inspection Photos  
Location Name: Sand River Unit 13  
Location ID: 313647



**Photo 4.** Taken from the western portion of the former well. Non-uniform vegetative cover at the former well location. Additional reclamation activities are required.

Inspection Photos  
Location Name: Sand River Unit 13  
Location ID: 313647



**Photo 5.** Taken from the eastern portion of the former well. See comments in Photo 4.