

# Final Reclamation and Stormwater Inspection

Date: 01/03/2023

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313663

Inspection Document #: 708200853

Morgan County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Sand River Unit #2  
Location ID: 313663



**Photo 1.** Stormwater erosion degradation (e.g. gullying) occurring on the access road, which has not been contoured or regraded to reflect pre-disturbance levels.

Inspection Photos  
Location Name: Sand River Unit #2  
Location ID: 313663



**Photo 2.** Southern portion of the location. The location is not progressing towards Rule 1004 standards as evidenced by a predominant vegetative cover of undesirable species (e.g. russian thistle and kochia). Additionally, the location has not been contoured or regraded to reflect pre-disturbance levels.

Inspection Photos  
Location Name: Sand River Unit #2  
Location ID: 313663



**Photo 3.** Eastern portion of the location; see comments in Photo 1.

Inspection Photos  
Location Name: Sand River Unit #2  
Location ID: 313663



**Photo 4.** Northern portion of the location; see comments in Photo 2.

Inspection Photos  
Location Name: Sand River Unit #2  
Location ID: 313663



**Photo 5.** Western portion of the location; see comments in Photo 2.

Inspection Photos  
Location Name: Sand River Unit #2  
Location ID: 313663



**Photo 6.** Area around the former wellhead is primarily bare/exposed soils.