

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 2084 From entrance to location




Photo # 2085 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 2086 Location



Photo # 2087 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 2088 Location

Photo # 2089 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 2090 Location



Photo # 2091 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



Photo # 2092 Location



Photo # 2093 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 19-2 (PJ19) Pad

Location #: 417538



**Photo # 2094 Flowline heating insulation open ended/wildlife hazard**



**Photo # 2095 Daybreak FEE 19-8 bradenhead connected to flowline/no FORM 4 Sundry**