

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2024

Submitted Date:

01/04/2024

Document Number:

693806571**FIELD INSPECTION FORM**Loc ID 322429 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS ST STE 6161City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Arnim, Rees	713-469-0275	rarnim@locin.energy	Director of Engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119495	PIT	AC	03/27/2017		-	Federal #3-11-8-104 119495	AC
210481	WELL	SI	06/01/2020	GW	045-06237	FEDERAL 3-11-8-104	TA

General Comment:

ECMC staff performed a routine field inspection on 1/3/2024.
Issues were found requiring corrective action. See inspection text and photos for details.
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action			Date:	
Type	Main			
comment:				
Corrective Action			Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign not updated to reflect current operator and emergency contact information.			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 02/11/2024
Emergency Contact Number:				
Comment:	see above			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Pump jack in shed with hogwire & T-post			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	1 gas meter shed removed since previous inspection.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 0			
Comment:	Separator removed since last inspection			
Corrective Action:				Date:

Type: Flow Line	# 9	
Comment:	Various size risers left in place from production equipment removal	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		39.381611,-108.963760
Comment:	Disconnected				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Fence and berms removed.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	119495	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	210481	Type:	WELL	API Number:	045-06237	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED									
Comment: Form 6 Doc#403334306 approved 5/9/2023. Expired 11/8/2023.									
Corrective Action: Contact NW area engineer aaron.katz@state.co.us Date: 01/11/2024									
BradenHead									
Date of Last Brhd Test: 05/24/2022 Annual Brhd Completed? No									
Last Brhd Test Results Initial Surf Csg Pressure: 260 Fluid Type: NONE									
End Surf Csg Pressure: 1									
Comment:									
Corrective Action: Date:									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>119495</u>	Lat: <u>39.381543</u>	Long: <u>-108.964161</u>
-----------------------------	------------------	-----------------------	-----------------------	--------------------------

Reference Point: SE Other: Length: 16 Width: 16

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard:

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403645414	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6381990
693806578	Inspection photos 1/3/2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6381939