

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2024

Submitted Date:

01/13/2024

Document Number:

707602233

FIELD INSPECTION FORM

Loc ID 483510 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484003	WELL	AP	03/13/2023		123-52073	Bishop A18-724	DG

General Comment:

This is a DRILLING inspection.

Well(s): 1: Drilling | DG.

New well GPS coordinates: 40.505383 / -104.585419

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Access / Entrance; site safety signage posted.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	OTHER		
Comment:	Sound monitors installed outside at 4 corners of sound walls. Gas monitors installed. Enhanced sound barriers installed. Low profile lighting installed for after dusk operations.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	LOCATION		
Comment:	Sound walls on 4 sides of location.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	484003	Type:	WELL	API Number:	123-52073	Status:	AP	Insp. Status:	DG
Well Drilling									
Rig:	Rig Name: Patterson UTI 268		Pusher/Rig Manager: John Drahota						
	Permit Posted: SATISFACTORY		Access Sign: SATISFACTORY						
Well Control Equipment:									
	Pipe Ram:	YES	Blind Ram:	YES	Hydril Type:	YES			
	Pressure Test BOP:	Pass	Test Pressure PSI:	5000	Safety Plan:	YES			
Drill Fluids Management:									
	Lined Pit:		Unlined Pit:		Closed Loop:	YES	Semi-Closed Loop:		
	Multi-Well:	YES	Disposal Location:	Waste Management LLC					
Comment:	<div>At the time of inspection: Drilling: 17,562' TD. Running casing: 9,383'. Well is #1 of 16 to be drilled. Sound monitors installed outside at 4 corners of sound walls. Gas monitors installed. Enhanced sound barriers installed. Low profile lighting installed for after dusk operations. Site safety plan posted.</div>								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/12/2024 at approximately 14:14 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: A07-01/Pad Location ID: 483510 Well Name(s): Bishop A18-724. API: 123-52073. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Drilling DG. New well GPS coordinates: 40.505383 / -104.585419</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/13/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602234	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6392262