

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC ACCO TOSCO W-21-34 Pad

Location #: 335219



**Location Overview: Location is within High Priority/Density
Habitat areas. Location is within Rule 411a Surface Water
External Buffer.**

Section/Township/Range: 34 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC ACCO TOSCO W-21-34 Pad
Location #: 335219



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC ACCO TOSCO W-21-34 Pad
Location #: 335219



Photo # 2506 Erosion & transport of sediment/insufficient BMP's (S/SE area of location on slope behind separator & production tank.)



Photo # 2507 Erosion & transport of sediment/insufficient BMP's (S/SE area of location on slope behind separator & production tank.)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC ACCO TOSCO W-21-34 Pad
Location #: 335219



Photo # 2508 Erosion & transport of sediment/insufficient BMP's (S/SE area of location on slope behind separator & production tank.)



Photo # 2509 Erosion & transport of sediment/insufficient BMP's (S/SE area of location on slope behind separator & production tank.)