

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Secondary Containment; see photos		
Corrective Action:	Comply with Rule 606	Date:	01/29/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	TA Wellhead		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297179 Type: WELL API Number: 123-27004 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - 05.26.2020. Form 6A 403118488 dated 08.16.2022 with a Plug Due Date of 12.31.2030

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection	petrie	01/08/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403648403	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6385757
696305710	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6385753