

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2023

Submitted Date:

01/15/2024

Document Number:

698601435**FIELD INSPECTION FORM**Loc ID 303136 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252528	WELL	PR	12/01/2021	GW	125-06404	G. BRETHAUER 1-24	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard label/sign at tank is faded and unreadable.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/15/2024
Type	OTHER		
Comment:	Well sign posted at gas meter run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign located at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on both the Well location and Meter Shed signs.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well site.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Post and wire fencing around remote metering shed is down. Post rotted off at surface.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Stock panel fencing at production tank.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Tubing appears to be in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Bradenhead plumbed to surface.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Remote Gas Meter Run located on CR M. Gas Meter Run. Chart in Meter Box dated 12-1-23. Meter Calibration/Test Log dated 10-16-23. Well Inlet Valve open. Gas Outlet Valve open.	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:	Located inside meter shed.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Separator/Meter Shed at remote Gas Meter Run.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV FIBERGLASS		,
Comment:	Content/Quantity/Hazard label and sign at tank unreadable.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	252528	Type:	WELL	API Number:	125-06404	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Remote Gas Meter Run located on CR M. Gas Meter Run. Chart in Meter Box dated 12-1-23. Meter Calibration/Test Log dated 10-16-23. Well Inlet Valve open. Gas Outlet Valve open.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601488	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6393058