

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 2667 From entrance to location



Photo # 2668 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 2669 Location



Photo # 2670 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Jan 11, 2024 at 3:32:27 PM
CO



Jan 11, 2024 at 3:31:33 PM
CO

Photo # 2671 Location

Photo # 2672 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 2673 PRV & rupture disc vent lines lack caps



Photo # 2674 PRV & rupture disc vent lines lack caps

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510




Photo # 2675 Tank label losing adhesion