

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2024

Submitted Date:

01/15/2024

Document Number:

708902790**FIELD INSPECTION FORM**Loc ID 324439 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**21 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296739	WELL	PR	04/26/2011	GW	045-16111	HILTON 23-1	PR
417579	WELL	PR	02/01/2020	GW	045-19563	CDOW KP 21-26	PR
417597	WELL	PR	10/01/2020	GW	045-19569	CDOW KP 414-23	PR
417598	WELL	PR	11/30/2010	GW	045-19570	CDOW KP 433-23	PR
417599	WELL	PR	01/31/2011	GW	045-19571	CDOW KP 534-23	PR

**General Comment:****CECMC Inspection Report Summary**

On 01/09/2024 at approximately 10:52 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC KP 24-23 Pad.

Location # 324439 in Garfield County Colorado.

Please refer to inspection 708900752 conducted on 06/12/2023, previous corrective actions have been completed.

Location is within High Priority/Density/Black Bear/NSO Habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Housekeeping - Dead weeds/debris in secondary containment with a CA date of 01/22/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Dead weeds/debris in secondary containment		
Corrective Action:	Comply with CECMC rules regarding debris		Date: 01/22/2024
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLS	HEATED STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	4	300 BBLS	STEEL AST		,		
Comment:		Centralized containment					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent					
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	5	300 BBLS	HEATED STEEL AST		,		
Comment:		Centralized containment					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent					
Comment:							
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	296739	Type:	WELL	API Number:	045-16111	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417579	Type:	WELL	API Number:	045-19563	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417597	Type:	WELL	API Number:	045-19569	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417598	Type:	WELL	API Number:	045-19570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417599	Type:	WELL	API Number:	045-19571	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Limited Stormwater inspection due to snow

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	01/15/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902791	Inspection 708902790 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6393486">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6393486</a>
708902792	Inspection 708902790 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6393487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6393487</a>