

Inspection Photos
Location Name: Kilker 1-15
Location ID: 321372



Pic 1 Wellhead



Pic 2 stained soil / leak near tank

Inspection Photos
Location Name: Kilker 1-15
Location ID: 321372



Pic 3 Stained soil / leak



Pic 4 Concrete BV

Inspection Photos
Location Name: Kilker 1-15
Location ID: 321372



Pic 5 Separator




Pic 6 ECD

Inspection Photos Location Name: Kilker 1-15 Location ID: 321372



Pic 7 GMR



Pic 8 gas meter run has not been calibrated 6/24/19.
 Calibration is needed.