

# Final Reclamation and Stormwater Inspection

Date: 1/11/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 331907

Inspection Document #: 713900261

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

Location Name: Brattain L-63N66W 12NENW

Location ID: 331907



**Photo 1.** The photo was taken at the well location facing North. The photo illustrates the access road into the location and the location are dominated by russian thistle and cereal rye.

**Photo 2.** The photo was taken at the well location facing East. The photo illustrates the location is dominated by russian thistle and cereal rye.

Inspection Photos

Location Name: Brattain L-63N66W 12NENW

Location ID: 331907



**Photo 3.** The photo was taken at the well location facing South.  
Refer to the comment from photo 2.

**Photo 4.** The photo was taken at the well location facing West.  
Refer to the comment from photo 2.

Inspection Photos

Location Name: Brattain L-63N66W 12NENW

Location ID: 331907



**Photo 5.** The photo was taken at the well location facing North. The photo illustrates the access road.

**Photo 6.** The photo was taken at the tank battery location facing West. The photo illustrates equipment remains at the location.

Inspection Photos

Location Name: Brattain L-63N66W 12NENW

Location ID: 331907



**Photo 7.** The reference photo was taken near the well location facing Southeast.