

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 2996 From entrance to location



Photo # 2997 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 2998 Location



Photo # 2999 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 3000 Location




Photo # 3001 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 3002 Location



Photo # 3003 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 3004 Flowline heating insulation open ended/wildlife hazard



Photo # 3005 Flowline heating insulation open ended/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-15BB (PN30) Pad

Location #: 334060



Photo # 3006 Rupture disc vent line lacks cap



Photo # 3007 Rupture disc vent line lacks cap

