

Inspection Photos
Location Name: Robertson 1-31
API Number: 125-06813



1. Possible sign frame at well location missing sign.



2. View of wellhead.

Inspection Photos
Location Name: Robertson 1-31
API Number: 125-06813



3. Surface casing missing plug.



4. Closer view of surface casing open port.

Inspection Photos
Location Name: Robertson 1-31
API Number: 125-06813



5. Flowline riser at wellhead area with open ended T connection.



6. Additional view of Flowline riser open at T connection.

Inspection Photos
Location Name: Robertson 1-31
API Number: 125-06813



7. Well location overview.



8. Well location overview.