

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2023

Submitted Date:

01/17/2024

Document Number:

698601443

**FIELD INSPECTION FORM**Loc ID 304006 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 24045

Name of Operator: ROBERTSON\* DEXTER

Address: 320 EAST 8TH AVE

City: YUMA State: CO Zip: 80759

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
, Engineering		dnr_ecmc_engineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Robertson, Dexter	970-630-5487	Kit@yumarealty.net	Domestic Well Operator

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253916	WELL	AC	03/08/1996	DM	125-07794	ROBERTSON 13-31	DM

**General Comment:**

Routine Domestic Well Inspection.

No production related equipment noted at well location other than wellhead.

**Location****Lease Road:**

Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well Lease sign at wellhead is unreadable.		
Corrective Action:	Install sign to comply with Rule 605.d. See Inspection Report Attachment for Rule 605 Text.	Date:	02/21/2024

**Emergency Contact Number:**

Comment:	No Emergency Contact Number at well location.		
Corrective Action:	Install sign to comply with Rule 605.d.(2).See Inspection Report Attachment for Rule 605 Text.	Date:	02/21/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Wood post, steel panel, and wire livestock fencing. Damaged.		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 0		corrective date
Comment:	Removed. No Pumping Unit on site at time of inspection.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing removed from the wellbore. Casing valve closed.		
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	No Bradenhead valve visible at surface.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) See Field Inspection Report Attachment.		Date: 02/01/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					

Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	253916	Type:	WELL	API Number:	125-07794	Status:	AC	Insp. Status:	DM
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
<div><div>Comment:</div><div><p>Pump Jack has been removed. Rods, and tubing have been removed from the wellbore.</p><p>Domestic Well Operation dated 06/06/1999. Well Status as AC 3/8/1996.</p><p>Well was identified as Shut In during Inspection completed 10/26/2016 Document Number 679901973 and again during Inspection conducted 3/11/2022 Document Number 688312356 with well production equipment noted as removed.</p><p>At the time of this inspection the wellhead casing valve was closed. There is no MIT in Electronic Well File and based on information available Inspector believes Well was found in state of Temporary Abandonment.</p><p>Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.</p></div></div>									
<div><div>Corrective Action:</div><div><p>Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.</p></div><div>Date: 02/21/2024</div></div>									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No Stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601511	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396423">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396423</a>
698601512	Rule 419 Text	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396424">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396424</a>
698601513	Rule 605 Text	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396425">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396425</a>
698601515	Rule 417 Text	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396426">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6396426</a>