

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2024

Submitted Date:

01/18/2024

Document Number:

701007988

FIELD INSPECTION FORM

Loc ID 321711 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207831	WELL	TA	09/01/2018	GW	017-06766	FRONTERA 24-13 18	TA

General Comment:

[Routine Inspection](#)

Location

Lease Road:

Type	Access				
comment:	Gravel road through farm ground				
Corrective ActionL				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:	Lease sign by unit				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:					
Corrective Action:					Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL				
Comment:	Horsehead stored next to unit				
Corrective Action:				Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Pump Jack	# 1				
Comment:	American 228				
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	Electric panel and cathodic rectifier				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
------	--	--	--	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 207831 Type: WELL API Number: 017-06766 Status: TA Insp. Status: TA

Producing Well

Comment: Central tank battery for (Frontera Unit 13, 14, 15, 16, 17, 18, 19, 20) 3100' E @ 38.741730/-102.054260

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA time of inspection. Passing MIT performed on 11/7/22

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007993	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398548