

# Inspection Photos

1/16/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335070

**Inspection Doc:** 696205547

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335070



**Photo 1:** Photos taken from the west end of the working pad surface. Photos provide an overview of the Location from northwest, north, east to southeast.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335070



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335070



January 16, 2024

**Photo 3:** Photo taken from the interim areas on the east end of the Location, facing north. Photo shows vegetation within these areas are progressing towards ECMC 1003 Standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335070



**Photo 4:** Photos taken from the western interim areas of the Location. Areas are predominantly bare and exposed soils. Little to no desirable vegetative establishment is occurring in these areas. BMPs to minimize erosion, degradation and sediment transport also missing or insufficient; rill erosion observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335070



**Photo 5:** Photos taken from the working pad surface around the wells. Photos examples showing BMPs to stabilize the working pad surface are no longer in proper functioning condition; control measures to minimize tracking inadequate; control measures to minimize off-site sediment transport by equipment, such as vehicle tracking pad, also not observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources