


KT Resources LLC
 WRD Dow 20-11
 Loc ID: 316271



Calibration out of compliance

As signs are replaced additional information will be required

**KT Resources LLC
WRD Dow 20-11
Loc ID: 316271**



Staining under loadline pot



Open ended loadline

**KT Resources LLC
WRD Dow 20-11
Loc ID: 316271**



Leaking oil tank



Leaking tank

**KT Resources LLC
WRD Dow 20-11
Loc ID: 316271**



Location from Northwest corner



Location from Northeast corner

**KT Resources LLC
WRD Dow 20-11
Loc ID: 316271**



Location from Southeast corner

Location from Southwest corner