

Inspection Photos
Location: Cindy H 23-27
Facility ID: 307489



Photo 1 –Well Site Placard on Meter House

Photo 2 – Wellhead and equipment looking south west

Inspection Photos
Location: Cindy H 23-27
Facility ID: 307489



Photo 3 – Meter House looking north east



Photo 4 – Exhaust hose and Oil Diaper on location

Inspection Photos
Location: Cindy H 23-27
Facility ID: 307489



Photo 5 – Equipment

Photo 6 – Oil Leaking from Pumping Unit. Cement block/base and native ground are impacted.

Inspection Photos
Location: Cindy H 23-27
Facility ID: 307489



Photo 7 – Pit looking south



Photo 8 – Flowline to pit

Inspection Photos
Location: Cindy H 23-27
Facility ID: 307489



Photo 9 – Pit looking North

Photo 10 – Pit Fencing and equipment

Inspection Photos
Location: Cindy H 23-27
Facility ID: 307489



Photo 11 – Access road looking west