

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2024

Submitted Date:

01/19/2024

Document Number:

708902821**FIELD INSPECTION FORM**Loc ID 335357 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266780	WELL	PR	11/11/2003	GW	045-09182	PA 341-33	PR
267794	WELL	PR	05/07/2003	GW	045-09208	PA 41-33	PR
274813	WELL	PR	06/06/2005	GW	045-13393	PA 441-33	PR

General Comment:**CECMC Inspection Report Summary**

On 01/16/2024 at approximately 10:12 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC PA 41-33 Pad.

Location # 335357 in Garfield County Colorado.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is within Rule 411a Surface Water Internal Buffer.

Location is approximately 27 yards from a drainage that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

<u>Lease Road:</u>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<u>Signs/Marker:</u>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

<u>Spills:</u>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<u>Fencing/:</u>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 7		
Comment:	Marked		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Cataflow		
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	PA 441-33 well has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. Remaining 2 wells have Taylor Plugs located on bradenhead, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			

Inspected Facilities									
Facility ID:	266780	Type:	WELL	API Number:	045-09182	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID: 267794 Type: WELL API Number: 045-09208 Status: PR Insp. Status: PR									
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID: 274813 Type: WELL API Number: 045-13393 Status: PR Insp. Status: PR									
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Gravel				Sparse to none in sections
		Ditches				
		Culverts				
		Check Dams				
		Compaction				

Comment: Limited Stormwater inspection due to snow

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902822	Inspection 708902821 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6400558
708902823	Inspection 708902821 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6400559