

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2024

Submitted Date:

01/21/2024

Document Number:

708902845

**FIELD INSPECTION FORM**

Loc ID: 335436  
Inspector Name: Smelser, Wayne  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 17 Number of Comments  
 0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259730	WELL	PR	04/05/2001	GW	045-07776	PA 13-34	PR
272710	WELL	PR	02/17/2006	GW	045-10141	PA 413-34	PR
272711	WELL	PR	02/13/2006	GW	045-10140	PA 513-34	PR
274843	WELL	PR	02/06/2006	GW	045-13411	PA 514-34	PR

**General Comment:**

CECMC Inspection Report Summary  
 On 01/18/2024 at approximately 10:50 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC PA13-34 Pad. Location # 335436 in Garfield County Colorado.  
 Please refer to inspection 707800505 conducted on 07/28/2023, 2 of 3 previous corrective actions have been completed. Unable to verify status of Stormwater corrective action due to snow.  
 Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water Internal Buffer.  
 While there, I observed normal production operations.

This is a summary of inspection report.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	PA 13-34 & 513-34 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.  Remaning 2 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>259730</u>	Type:	<u>WELL</u>	API Number:	<u>045-07776</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>272710</u>	Type:	<u>WELL</u>	API Number:	<u>045-10141</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>272711</u>	Type:	<u>WELL</u>	API Number:	<u>045-10140</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>274843</u>	Type:	<u>WELL</u>	API Number:	<u>045-13411</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				Sparse to none in visible areas
		Compaction				
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Any corrective actions from previous inspections that have not been addressed are still applicable.	smelserw	01/21/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902846	Inspection 708902845 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6401201">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6401201</a>
708902847	Inspection 708902845 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6401202">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6401202</a>