

# Inspection Photos

Loc: 484360

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 1/18/2024

County: LAS ANIMAS




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest toward the access road and County Road 177. There is vehicle rutting and tracking of sediment onto the County Road. BMP's must installed to prevent sediment tracking and road degradation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

## Inspection Photos



**Photo 2.** Facing west by the location. There is still tree debris that has not been removed..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

Inspection Photos



**Photo 3.** Facing west toward the location. The bags of cement have been removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

## Inspection Photos



**Photo 4.** Facing toward the well. The excavated area near the well has been backfilled. Most of the rock debris has been removed. It is unknown what topsoil material was replaced since it was not properly salvaged.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

## Inspection Photos



**Photo 5.** Facing northwest at the location where cuttings were improperly stored. It appears most of the drill cuttings have been removed. There are still no stormwater controls present at the northwest downslope side of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

Inspection Photos



**Photo 6.** Facing toward the northwest side of the location. There is still a reddish color in this area that remains which is indicative of the drill cuttings.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

## Inspection Photos



**Photo 7.** Facing southeast at the location. There is still a reddish color in this area that remains which is indicative of the drill cuttings.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

## Inspection Photos



**Photo 8.** Facing southwest at the northwest side of the location. There are still no stormwater controls present at the northwest downslope side of the location. Previous corrective action has not been completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

## Inspection Photos



**Photo 9.** Facing southeast at the west side of the location. The perimeter wattles end at this point and do not protect the northwest downhill perimeter where loose soil are present.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

Inspection Photos



**Photo 10.** Facing east toward the disturbed location. All disturbed soils will need to be decompacted and reclaimed prior to the upcoming growing season.



## Inspection Photos



**Photo 11.** Facing northeast toward the disturbed location. All disturbed soils will need to be decompacted and reclaimed prior to the upcoming growing season



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024

Inspection Photos



**Photo 12.** Facing east toward the flowline disturbance. The disturbance has been graded and rocks, tree debris appear to be mostly removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484360 | Date: 1/18/2024