

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

11/22/2023

Document Number:

403581851

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10575 Contact Person: James Miller
Company Name: 8 NORTH LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 460765 Location Type: Production Facilities
Name: DF Ranch 10-11, 13, 42, 44 Number:
County: WELD
Qtr Qtr: NENE Section: 10 Township: 11N Range: 61W Meridian: 6
Latitude: 40.936004 Longitude: -104.182587

Description of Corrosion Protection

8 North's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, 8 North will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. 8 North retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

8 North's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, 8 North ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461368 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 415381 Location Type: Well Site   
Name: DF RANCH Number: 1161-10-13  
County: WELD No Location ID  
Qtr Qtr: SWNE Section: 10 Township: 11N Range: 61W Meridian: 6  
Latitude: 40.939460 Longitude: -104.189350

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375  
Bedding Material: Native Materials Date Construction Completed: 04/25/2010  
Maximum Anticipated Operating Pressure (PSI): 130 Testing PSI: 130  
Test Date: 09/20/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 08/18/2020

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Flowline/Riser is locked out and tagged out.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 461369 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 302923 Location Type: Well Site   
Name: DF RANCH-611N61W Number: 10SESE  
County: WELD No Location ID  
Qtr Qtr: SESE Section: 10 Township: 11N Range: 61W Meridian: 6  
Latitude: 40.930460 Longitude: -104.184390

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375  
Bedding Material: Native Materials Date Construction Completed: 05/10/2009  
Maximum Anticipated Operating Pressure (PSI): 141 Testing PSI: 141  
Test Date: 09/12/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 04/05/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

The entire 2" steel line was pulled and removed. The 1" poly line was unable to be pulled and was cut and capped below grade.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 461370 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 302813 Location Type: Well Site   
Name: DF RANCH-611N61W Number: 10NENE  
County: WELD No Location ID  
Qtr Qtr: NENE Section: 10 Township: 11N Range: 61W Meridian: 6  
Latitude: 40.941800 Longitude: -104.184310

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375  
Bedding Material: Native Materials Date Construction Completed: 04/27/2009  
Maximum Anticipated Operating Pressure (PSI): 120 Testing PSI: 120  
Test Date: 09/10/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 02/07/2022

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

The subject flowline (12329869FL) was removed in its entirety. The 3" steel-flowline (buried ~4' deep) was cut and pulled via bellholes. Approximately 2860' of flowline was removed. The bellholes were backfilled and graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 461371 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 302922 Location Type: Well Site   
Name: DF RANCH-611N61W Number: 10NWSE  
County: WELD No Location ID  
Qtr Qtr: NWSE Section: 10 Township: 11N Range: 61W Meridian: 6  
Latitude: 40.934010 Longitude: -104.189130

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375  
Bedding Material: Native Materials Date Construction Completed: 05/22/2009  
Maximum Anticipated Operating Pressure (PSI): 141 Testing PSI: 141  
Test Date: 09/10/2018

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 09/04/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).  
(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the DF RANCH 10-42 (05-123-30030) was removed in its entirety via the open trench method. The trench was backfilled and the land surface graded.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowline was removed:  
12330030FL: serviced DF RANCH 10-42 (05-123-30030)  
Updated GIS data attached. Because the previously reported abandonment of the 12330031FL was removed prior to GIS requirements, updated GIS data for this specific line is not available.  
All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 11/22/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  Director of COGCC Date: 1/22/2024

**Conditions of Approval**

**COA Type**

**Description**

--	--

**Attachment Check List**

**Att Doc Num**

**Name**

403581851	Form44 Submitted
403594301	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)