



**Location**

Overall Good:

**Signs/Marker:**

Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unused Secondary Containments in the Northeast Corner of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	02/09/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Instrumental Air Compression Unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical and Automation Equipement		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.458974,-104.431298
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 480889 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: [PR - Active Production Facility](#)

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Unused Secondary Containments in NE Corner of Location</a>	petrie	01/16/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403656661	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6394791">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6394791</a>
696305793	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6394789">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6394789</a>