

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2024

Submitted Date:

01/23/2024

Document Number:

705000602**FIELD INSPECTION FORM**Loc ID 331239 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259663	WELL	SI	07/01/2021	GW	123-20363	HSR-TEETS 3-29A	PA
331239	LOCATION	AC			-	HSR - TEETS-62N67W 29NENW	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 259663 Type: WELL API Number: 123-20363 Status: SI Insp. Status: PA**Flowline**

#1	Type:Non-Well Site	of Lines
----	--------------------	----------

Flowline DescriptionFlowline Type: Non-Well Site Size: 2" Material: Carbon Steel
Variance: Age: Contents:Integrity SummaryFailures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well is plugged and abandoned (HSR Teets 3 29A); ECMC form 42 notice of start of plugging operations doc #403573328 received on 10/26/2023. The OLF has been AIP/ removed; bellhole excavations observed at flowline pipe removal pull points between WH & facility (backfilled). The facility/ tank battery is being decommissioned; tanks and equipment removed. On location flowlines (dump and process lines) have been removed. ECMC form 42 notice of flowline abandonment completed doc #403649341 received 01/09/2024. Fenced excavations observed at PA well and facility/ battery areas. Remediation work is in progress.

Corrective Action:

Date:

Facility ID: 331239 Type: LOCATION API Number: - Status: AC Insp. Status: EG**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403659473 received on 01/19/2024: On January 18, 2024, historically impacted soil was discovered following cut and cap operations at the Teets 3-29A wellhead location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	01/23/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000604	Signage at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6403789
705000605	View SW from wellhead to battery; OLF removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6403790
705000606	Excavations at facility/ battery; fenced	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6403791