


**Inspection Photos**  
**Location: Becks 41-16 and Becks 41-16 TR**  
**Facility ID: 334237**



**Photo 1 –Well Site Placard, WDID stickers are illegible**



**Photo 2 – Well Site Placard, WDID stickers are illegible**

**Inspection Photos**  
**Location: Becks 41-16 and Becks 41-16 TR**  
**Facility ID: 334237**



**Photo 3 – Spill at wellhead**



**Photo 4 – Location of Spill**



**Inspection Photos**  
**Location: Becks 41-16 and Becks 41-16 TR**  
**Facility ID: 334237**



**Photo 5 – Open End of Plugged Culvert at Lat 37.26438; Long -104.67228**



**Photo 6 – Plugged end of Culvert at Lat 37.26438; Long -104.67228**



**Inspection Photos**  
**Location: Becks 41-16 and Becks 41-16 TR**  
**Facility ID: 334237**



**Photo 7 – Oil Soils/Gravel**



**Photo 8 – Oil Soils/Gravel**



**Inspection Photos**  
**Location: Becks 41-16 and Becks 41-16 TR**  
**Facility ID: 334237**



**Photo 9 – Spill location**

