

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2024

Submitted Date:

01/23/2024

Document Number:

710500157**FIELD INSPECTION FORM**Loc ID 334237 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89193	WELL	PR	05/01/2022	CBM	071-06772	BECKS 41-16TR	EI
217833	WELL	PR	07/18/2021	CBM	071-06612	BECKS 41-16	EI
334237	LOCATION	AC			-	BECKS-632S65W 16NENE	EI

General Comment:

This is a follow-up Environmental inspection to Inspection # 710500104 conducted on the Becks 41-16 and Becks 41-16 Tr Active Well location, Location Id 334237 Located in Las Animas County Colorado.

Location**Lease Road:**

Type	Access		
comment:	At the time of inspection there was a plugged Culvert located at Lat 37.26438; Long -104.67228		
Corrective Action	Comply with Rule 1002.f.	Date:	02/07/2024

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Well Site Placards are located on the Meter house. WDID stickers associated with the Placards are illegible.		
Corrective Action:	Comply with Rule 605.g.	Date:	02/26/2024

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	Separator	<= 1 bbl		
Comment:	At the time of inspection, oily material was noted adjacent to the Meter house. Operator shall investigate the area to determine where the oily substance is originating. Operator shall file a Form 19 Per Rule 912.			
Corrective Action:	Comply with Rule 912.			Date: 01/24/2024
Produced Water	WELLHEAD			
Comment:	At the time of inspection, a produced water leak was observed near the Wellhead . ECMC staff contacted TJ Fernandez with ENR to report findings.			
Corrective Action:	Operator Submitted a Form 19 Initial for the Spill, which is under ongoing investigation. A supplemental Form 19 is due within 10 days of discovery.			Date: 01/29/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>89193</u>	Type: <u>WELL</u>	API Number: <u>071-06772</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>217833</u>	Type: <u>WELL</u>	API Number: <u>071-06612</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>334237</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

COGCC Comments

Comment	User	Date
There is a plugged Culvert located at Lat 37.26438; Long -104.67228 Comply with Rule 1002.f.	sanchezcc	01/23/2024
Well Site Placards are located on the Meter house. WDID stickers associated with the Placards are illegible.	sanchezcc	01/23/2024
At the time of inspection, oily material was noted adjacent to the Meter house. Operator shall investigate the area to determine where the oily substance is originating. Operator shall file a Form 19 Per Rule 912.	sanchezcc	01/23/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500159	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6403956