

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: PRONGHORN-65N61W 21NWNE**

**Loc ID: 302895**

**Inspection: 713900241**



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**



**Exhibit E**



**Exhibit F**

**CA:** This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within three months of plugging on cropland. Well was plugged 06/22/2018. The well location and access road have not been re-contoured or re-graded. The access road has subsided and the cut slope along the North side of the location has not been re-contoured. Cereal rye also is dominated across the well location and access road. Perform reclamation in accordance to Rule 1004.

**CA Resolution:** Operator has reported that the access road has been recontoured, and the location has been reseeded and straw crimped to establish vegetation to comply with Rule 1004.