

# Inspection Photos

Loc: 322234

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/18/2023

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast at the beginning of the access road. There is erosion occurring along the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:322234 | Date: 1/18/2024



## Inspection Photos



**Photo 2.** Facing southeast along the road. There are undesirable weeds growing along the road side that need to be removed/controlled..





## Inspection Photos



**Photo 3.** Facing south toward the location. The well has been plugged and abandoned however final reclamation has not yet been completed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:322234 | Date: 1/18/2024



## Inspection Photos



**Photo 4.** Facing southwest along the fill slope. The location will need to be recontoured back to the original slopes





## Inspection Photos



**Photo 5.** The electric utilities remain at the location and should have been removed with 3 months of abandonment. The entire powerline and poles servicing this location must be removed. There is a topsoil pile shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:322234 | Date: 1/18/2024



## Inspection Photos



**Photo 6.** Facing toward the south side of the location. There are tanks that have not been removed. All equipment should have been removed within 3 months of abandonment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:322234 | Date: 1/18/2024



## Inspection Photos



**Photo 7.** Upon closer inspection of the tanks there is a spill that had occurred at the tank outlet. Immediate clean up needs to be performed.





## Inspection Photos



**Photo 8.** Facing west at the south side of the location. There is an erosion channel shown at red arrow which will need to be repaired and stabilized.





## Inspection Photos



**Photo 9.** Facing southeast at the south side of the location. There is an erosion channel shown at red arrow which will need to be repaired and stabilized.





## Inspection Photos



**Photo 10.** Facing east along the cut slope. There is rilling erosion along the cut slope.





## Inspection Photos



**Photo 11.** Facing north along the cut slope. There cut slope is not stabilized.





## Inspection Photos



**Photo 12.** Facing south at the location standing from the top of the cut slope.

