

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2024

Submitted Date:

01/24/2024

Document Number:

709700334**FIELD INSPECTION FORM**Loc ID 335591 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10547Name of Operator: HELENA RESOURCES INCAddress: 2960 SIMMS DRCity: LAKEWOOD State: CO Zip: 80215**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|-------------------------------|---------|
| Pagano, Theodore | (970) 590-3944 | tapagano@helena-resources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 284353 | WELL | PR | 11/01/2020 | GW | 001-09563 | GUTHRIE 42-2 | PR |

General Comment:

| | | | | |
|--|----------------------------------|--------|--|-----------------|
| Location | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Adequate | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Adequate | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Pipe | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bradenhead | # 1 | | | corrective date |
| Comment: | Appears to be plumbed to surface | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Venting: | | | | |
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| | | | | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 284353 | Type: | WELL | API Number: | 001-09563 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

| COGCC Comments | | |
|--------------------|-------|------------|
| Comment | User | Date |
| Routine Inspection | huckk | 01/24/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 709700335 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405665 |