

Inspection Photos
Location Name: Adamic #1-20
Location ID: 322219



Photo 1 TNK BTRY




Photo 2 stained soil load line

Inspection Photos
Location Name: Adamic #1-20
Location ID: 322219



Photo 3 Stained soil and mechanical issue crude oil load lines.



Photo 4 Stained soil and mechanical issue crude oil load lines.

Inspection Photos
Location Name: Adamic #1-20
Location ID: 322219




Photo 5 Stained soil and mechanical issue crude oil load lines.




Photo 6 Stained soil mechanical issue well head leaking

Inspection Photos
Location Name: Adamic #1-20
Location ID: 322219



Photo 7 PU



Photo 8 Stained soil and mechanical issue crude oil load lines.