

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2024

Submitted Date:

01/18/2024

Document Number:

701007977**FIELD INSPECTION FORM**Loc ID 314219 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10227Name of Operator: CHOLLA PETROLEUM INCAddress: PO BOX 12208City: DALLAS State: TX Zip: 75225**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone        | Email                  | Comment |
|----------------|--------------|------------------------|---------|
| Obenchain, Tom | 214-455-4614 | tao@chollapetro.com    |         |
| Costa, Ryan    |              | ryan.costa@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 285480      | WELL | SI     | 07/01/2021  | GW         | 099-06889 | LUKIE-DO 2-24 | PA          |

**General Comment:**[Final Routine Inspection](#)

**Location**

|                    |                             |       |  |
|--------------------|-----------------------------|-------|--|
| <b>Lease Road:</b> |                             |       |  |
| Type               | Access                      |       |  |
| comment:           | Two track through grassland |       |  |
| Corrective Action  | L                           | Date: |  |

Overall Good: ☒

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                                   |                       |       |                 |
|-----------------------------------|-----------------------|-------|-----------------|
| <b>Equipment:</b>                 |                       |       | corrective date |
| Type: Ancillary equipment         | # 0                   |       |                 |
| Comment:                          | Removed from location |       |                 |
| Corrective Action:                |                       | Date: |                 |
| Type: Gas Meter Run               | # 0                   |       |                 |
| Comment:                          | Removed from location |       |                 |
| Corrective Action:                |                       | Date: |                 |
| Type: Horizontal Heated Separator | # 0                   |       |                 |
| Comment:                          | Removed from location |       |                 |
| Corrective Action:                |                       | Date: |                 |

**Tanks and Berms:**

|                    |                       |          |                |         |                       |       |
|--------------------|-----------------------|----------|----------------|---------|-----------------------|-------|
| Contents           | #                     | Capacity | Type           | Tank ID | SE GPS                |       |
| PRODUCED WATER     | 0                     | 200 BBLs | FIBERGLASS AST |         | 38.212090,-102.648770 |       |
| Comment:           | Removed from location |          |                |         |                       |       |
| Corrective Action: |                       |          |                |         |                       | Date: |

**Paint**

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

**Berms**

|          |          |                     |                     |             |
|----------|----------|---------------------|---------------------|-------------|
| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|          |          |                     |                     |             |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |  |  |
|--|--|--|
|  |  |  |
|--|--|--|

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 285480 | Type: | WELL | API Number: | 099-06889 | Status: | SI | Insp. Status: | PA |

|  |
|--|
|  |
|--|

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use:                     

Comment:                     

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment                     

Corrective Action                      Date                     

1002b. SOIL REMOVAL AND SEGREGATION                     

Comment                     

Corrective Action                      Date                     

1002c. PROTECTION OF SOILS                     

Comment                     

Corrective Action                      Date                     

1002E. SURFACE DISTRURBANCE MINIMIZATION                     

Comment                     

Corrective Action                      Date                     

1003a. Waste and Debris removed?                     

Comment                     

Corrective Action                      Date                     

Unused or unneeded equipment onsite?                     

Comment                     

Corrective Action                      Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment                     

Corrective Action                      Date                     

Guy line anchors marked?                     

Comment                     

Corrective Action                      Date

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built In

Access Roads Regraded In Contoured In Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation In Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% In Cropland: perennial forage \_\_\_\_\_

Weeds present In Process Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: Well has been plugged. Wellhead has been cut, capped and covered. Location has been ripped and mulched. Form 6S (403317791) is In Process. Equipment has been removed from location and ready for final reclamation. Final reclamation will be verified by reclamation specialist

Corrective Action: Continue with final reclamation process Date \_\_\_\_\_

|                           |            |                                 |  |                     |  |
|---------------------------|------------|---------------------------------|--|---------------------|--|
| Overall Final Reclamation | In Process | Well Release on Active Location |  | Multi-Well Location |  |
|---------------------------|------------|---------------------------------|--|---------------------|--|

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Mulching         | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403659466    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398552">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398552</a> |
| 701008000    | location photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398541">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398541</a> |