

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2024

Submitted Date:

01/19/2024

Document Number:

714000316

FIELD INSPECTION FORMLoc ID 325568 Inspector Name: Mcdonough, Corey On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES LLC

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	All Inspections
Williford, Hearne		hwilli@swbell.net	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215019	WELL	PR	07/31/2007	OW	067-06624	M & M 3	RI

General Comment:

On 1/17/2024 Reclamation Specialist Corey McDonough conducted a Storm water and Reclamation Inspection at Williford Resources LLC's M&M 3 location in La Plata County, Colorado. This is a follow up inspection to doc # 693901153.

During the inspection the following compliance issues were observed

- Debris
- Unused equipment

Refer to the "Good Housekeeping" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable; The "Date of Discovery" is being provided as the corrective action date for all new observed compliance issues. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Inspection doc #693901153 observed equipment stored on the disturbance and required compliance by 9/26/2018. It was observed in this inspection that equipment remains on location. Original CA date remains applicable.		
Corrective Action:	Remove unused equipment per rule 606.	Date:	09/26/2018
Type	DEBRIS		
Comment:	Weedy debris observed around active equipment.		
Corrective Action:	Comply with rule 606, remove and properly dispose of debris.	Date:	01/17/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215019	Type:	WELL	API Number:	067-06624	Status:	PR	Insp. Status:	RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403660360	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6399683
714000323	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6399662