

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF06D J27 595 Pad

Location #: 335787



Photo # 3937 From entrance to location




Photo # 3938 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF06D J27 595 Pad

Location #: 335787



Photo # 3939 Location




Photo # 3940 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF06D J27 595 Pad

Location #: 335787




Photo # 3941 Location



Photo # 3942 Wellhead signage insufficient/sign does not conform to CECMC rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF06D J27 595 Pad

Location #: 335787



Photo # 3943 Wellhead signage insufficient/sign does not conform to CECMC rules



Photo # 3944 Wellhead signage insufficient/sign does not conform to CECMC rules