

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2024

Submitted Date:

01/26/2024

Document Number:

694500615**FIELD INSPECTION FORM**Loc ID 324639 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-----------------------------|---------|
| Afton Iiams | | aiiams@foundationenergy.com | |
| Smith, James | 972-707-2595 | jsmith@foundationenergy.com | |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Kelly Elliot | | kaelliott@blm.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 212231 | WELL | PA | 05/19/2021 | OW | 057-06124 | ALLARD 30-8-5 | EI |

General Comment:

ON 1/25/24 ECMC staff, Kris Neidel inspected location 324639, Allard 30-8-5. The location is part of REM Project # 17342. At the time of inspection, the location was under snow cover and drifted snow. weather was overcast and 22 degrees. The well has been plugged, no process equipment is on the location or at the site of the former wellhead. There is a pile of stockpiled soil that was reported in REM project 17342, the pile has; a plastic fence, straw waddles and an electric wire running the perimeter. The electric wire and fencing is fallen down in the snow. Corrective Actions: Per 913.b.(5) Ensure that livestock can not access or surface water to contact the stockpiled soil. See attached photos.

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 212231 | Type: | WELL | API Number: | 057-06124 | Status: | PA | Insp. Status: | EI |

| |
|--|
| |
|--|

Environmental**Waste Management:**

| Type | Management | Condition | GPS (Lat) | (Long) |
|-------------------|---|------------|-----------|------------------|
| Oily Soil | Piles | Inadequate | | |
| Comment | There is a pile of stockpiled soil that was reported in REM project 17342, the pile has; a plastic fence, straw waddles and an electric wire running the perimeter. | | | |
| Corrective Action | Per 913.b.(5)Ensure that livestock can not access or surface water to contact the stockpiled soil. | | | Date: 02/02/2024 |

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): Comment: Pilot: Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694500616 | photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408526 |