

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403651070

Date Received:

01/11/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205330

Inspection Date: 10/09/2023

FIR Submit Date: 10/11/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335886

Location Name: Berry Number: 111 697 County: _____

Qtrqr: NESE Sec: 11 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.534660 Longitude: -108.180740

FACILITY - API Number: 05-045-00 Facility ID: 335886

Facility Name: Berry Number: 111 697

Qtrqr: NESE Sec: 11 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.534660 Longitude: -108.180740

CORRECTIVE ACTIONS:

2 ☒ CA# 183796

Corrective Action: Comply with Rule 1002.f- install and/or repair stormwater and erosion control measures in accordance with good engineering practices.

Date: 10/09/2023

Response: CA COMPLETED

Date of Completion: 11/10/2023

Operator
Comment:

This location was cross ripped to address seeding, and mulch, and erosion. Erosion logs on the lower perimeter of the location (fill slope) are in place. Rule 1002.f.(2) qualifies stormwater management with: "BMPs shall be selected based on site-specific conditions, such as slope, vegetation cover, and proximity to water bodies." A Runon control on top of location is functioning and adequate (ditch). Therefore, Caerus does not feel that erosion logs on the upper perimeter (cut slope) are reasonable or necessary on this specific location. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 1/11/2024 7:49:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403651070	FIR RESOLUTION SUBMITTED
403651071	Cross Ripped and Seeded
403651072	Cross Ripped and Seeded

Total Attach: 3 Files