

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/26/2024

Document Number:

713300574

FIELD INSPECTION FORMLoc ID 305213 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275698	WELL	SI	10/01/2023	OW	123-22658	REISBECK 9-18	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	DEAD overgrown vegetation and trash		
Corrective Action:	Comply with Rule 606	Date:	02/02/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	automation panel		
Corrective Action:		Date:	
Type: Plunger Lift	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 275698 Type: WELL API Number: 123-22658 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Valves appeared to be closed at time of inspection

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 06/14/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 5Fluid Type: WaterEnd Surf Csg Pressure: --

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Friday, January 26, 2024, at approximately 14:30, I, Inspector Michael Kester, conducted an on-site inspection. Location: Reisbeck 9-18 Operator: Kerr McGee API#: 123-22658 County: Weld While there, I observed remote located well. During this inspection the following possible compliance issues were observed: Debris, Comply with Rule, corrective action date 2-2-2024 photo 1 & 2 Weather conditions: over cast and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kestern	01/26/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300578	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408839