

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 3971 From entrance to location



Photo # 3972 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 3973 Location



Photo # 3974 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 3975 Location



Photo # 3976 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 3977 Location




Photo # 3978 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1367 From inspection 708902651 conducted on 12/28/2023 Wellhead sign lacks required info/sign in not in compliance with CECMC rules



Photo # 3979 Wellhead sign lacks required info/sign in not in compliance with CECMC rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1368 From inspection 708902651 conducted on 12/28/2023 Wellhead sign lacks required info/sign in not in compliance with CECMC rules



Photo # 3980 Wellhead sign lacks required info/sign in not in compliance with CECMC rules



Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 1369 From inspection 708902651 conducted on 12/28/2023 Wellhead sign lacks required info/sign in not in compliance with CECMC rules




Photo # 3981 Wellhead sign lacks required info/sign in not in compliance with CECMC rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad

Location #: 335828



Photo # 3982 Wellhead sign lacks required info/sign in not in compliance with CECMC rules