

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4009 From entrance to location



Photo # 4010 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4011 Location




Photo # 4012 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4013 Location



Photo # 4014 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4015 Debris



Photo # 4016 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1207 From inspection 708902630 conducted on 12/28/2023 All wellhead signs on location lack required information/wellhead signage insufficient/signs are not in compliance with CECMC rules



Photo # 4017 All wellhead signs on location lack required information/wellhead signage insufficient/signs are not in compliance with CECMC rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1208 From inspection 708902630 conducted on 12/28/2023 All wellhead signs on location lack required information/wellhead signage insufficient/signs are not in compliance with CECMC rules



Photo # 4018 All wellhead signs on location lack required information/wellhead signage insufficient/signs are not in compliance with CECMC rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1209 From inspection 708902630 conducted on 12/28/2023 All wellhead signs on location lack required information/wellhead signage insufficient/signs are not in compliance with CECMC rules




Photo # 4019 All wellhead signs on location lack required information/wellhead signage insufficient/signs are not in compliance with CECMC rules